

Justin T. Bailey Esq., NY Bar No. 5034269  
David W. Hannum Esq., NJ Bar No. 036962006  
Perry R. Sanders Jr. Esq., LA Bar No. 01577  
Sanders Law Firm, LLC  
31 N Tejon Street, Suite 400  
Colorado Springs, CO 80903  
T: (719) 630-1556  
F: (719) 630-7004

**ATTORNEYS FOR PLAINTIFFS**

**IN THE UNITED STATES DISTRICT COURT SOUTHERN  
DISTRICT OF NEW YORK**

**IN RE:**

**GENERAL MOTORS LLC IGNITION  
SWITCH LITIGATION**

**MDL NO. 2543**

**HON. JESSE M. FURMAN**

**THIS DOCUMENT RELATES TO:**

Haley Campbell, Together with all  
individuals whose names appear on the  
attached Exhibit "A"

Plaintiffs,

v.

**GENERAL MOTORS LLC**

Defendant.

Case No.

**COMPLAINT AND JURY TRIAL DEMAND**

**I. PRELIMINARY STATEMENT**

1. The Named Plaintiffs' causes of action are brought solely against General Motors, LLC ("Defendant," "GM," "Defendant GM," or "New GM"). Plaintiffs do not assert any causes of action against General Motors Corporation ("Old GM").
2. Any references to General Motors Corporation, Old GM, or pre-sale order conduct in this Complaint are (a) for background and reference purposes only; or (b) referenced for the post-sale accidents resulting in person injury and/or wrongful death claims, as asserted by the Plaintiffs listed in Exhibit "A." That is, under the June 26, 2009 Amended and Restated Master Sale and Purchase Agreement ("Agreement") wherein New GM acquired certain Old GM assets, New GM expressly assumed liability for post-sale accidents involving Old GM vehicles causing personal injury, loss of life or property damage. New GM also acquired knowledge of Old GM's activities and the defective ignition switch via the mind of the employees, officers, managers, books and records obtained and/or acquired as a result of the Agreement and subsequent Sale Order. Thus, the duties of Old GM are part of the foundation for the liability assumed by New GM. Further, as identified therein, the Named Plaintiffs have claims for post-sale accidents involving Old GM vehicles that caused personal injury, loss of life or property damage and New GM is therefore expressly liable to the Named Plaintiffs.

**II. INTRODUCTION**

3. At any given moment, an ignition switch in a wide variety of General Motors vehicles could fail, killing or maiming countless individuals. The disastrous system failures in GM vehicles are triggered by something as simple as a key chain on the vehicle's key or a bump in the road, as the ignition switch shifts from the "run" position into the "accessory/off" position, with a corresponding reduction or loss of power. See March 11, 2014 Letter from New GM to Ms. Nancy Lewis re: NHTSA Recall No. 14V-047, at p. 1 ("Until the recall repairs have been performed, it is very important that customers remove all items from their key rings, leaving only the vehicle key."); see also New GM Safety Recall Notice ("Th[e] risk increases if your key ring is carrying added weight (such as more keys or the key fob) or your vehicle experiences rough road conditions or other jarring or impact related events.").
4. Yet, New GM also admits to its customers that lightening the key chain may not help as "rough road conditions or other jarring impacted related events" could cause the vehicle to experience full loss of power, steering, braking and air bag deployment. See March 24, 2014 Letter from Senator Blumenthal to Attorney General Holder. Appropriately, the Old GM engineer who designed the ignition switch called it "the switch from hell." Report to the Board of Directors of General Motors Company Regarding the Ignition Switch Recalls, authored by Anton R. Valukas of Jenner & Block (May 29, 2014) (or "Valukas Report") at p. 5.
5. New GM's refusal to honestly speak about the defective ignition switch has gone on too long—more than four and a half years since Old GM filed for bankruptcy.

Throughout that time, New GM knew of the life-threatening danger its defective ignition switches can cause, and yet concealed the risk from drivers. Considering both the time that Old GM discovered the ignition switch defect and the time that New GM learned about it, thirteen years have passed. New GM belatedly admits that there has been a death for every year of their collective silence. But a recent report suggests that the death toll is exponentially higher than New GM admits, with the number actually in the hundreds. See March 13, 2014 Letter from Center for Auto Safety to the Honorable David J. Friedman (“On March 7, the Center for Auto Safety (CAS) wrote you about NHTSA’s failure to utilize its Special Crash Investigations (SCI) of 2005 Cobalt’s and 2004 Ions and Early Warnings Reports (EWR) of death claims filed by GM to open a defect investigation and order a recall. Examination of NHTSA’s Fatal Analysis Reporting Systems (FARS) reveals 303 deaths of front seat occupants in the recalled 2005-07 Cobalt’s and 2003-07 Ions where the airbag failed to deploy in non-rear impact crashes.”). This new figure is drawn from data on only two of the many recalled models, the Chevrolet Cobalt and Saturn Ion. The death toll is expected to increase significantly as the full gamut of defective vehicles and incidents come to light.

6. As of February 4, 2015, Kenneth Feinberg, the administrator of GM’s ignition switch compensation fund, has already deemed 51 death claims eligible for compensation since he began accepting applications in August. This total is “likely to rise” as the fund considers newly filed claims.

### III. PARTIES

7. The Named Plaintiffs are those individuals listed on the attached Exhibit “A”.

8. The Named Plaintiffs assert claims against Defendant General Motors LLC for personal injury and/or wrongful death stemming from post-sale accidents—that is, the accidents in question occurred on or after July 10, 2009.

9. The Named Plaintiffs’ personal injury and/or wrongful death claims involve one or more of the following GM vehicles: **2010-2014 Chevrolet Camaro; 2005-2010 Pontiac G5; 2005-2009 Buick LaCrosse; 2006-2011 Buick Lucerne; 2000-2005 Cadillac Deville; 2006-2011 Cadillac DTS; 2006-2014 Chevrolet Impala; 2006-2007 Chevrolet Monte Carlo; 2003-2014 Cadillac CTS; 2004-2006 Cadillac SRX; 1997-2005 Chevrolet Malibu Classic; 2000-2005 Chevrolet Impala; 2000-2005 Chevrolet Monte Carlo; 2000-2005 Pontiac Grand Am; 2004-2008 Pontiac Grand Prix; 1998-2002 Oldsmobile Intrigue; and 1999- 2004 Oldsmobile Alero.**

10. Defendant General Motors LLC is a Delaware limited liability company, and does business in all fifty states. General Motors LLC’s principal place of business is at 300 Renaissance Center Detroit, Michigan.

11. General Motors LLC is a limited liability company with one member: General

Motors Holding LLC. General Motors Holding LLC is a citizen of Delaware and Michigan, and is a holding company and direct parent of General Motors LLC. General Motors Holding LLC is a limited liability company with one member: General Motors Company. General Motors Company is a citizen of Delaware and Michigan and is publicly traded.

12. General Motors Corporation was a Delaware corporation with its headquarters in Detroit, Michigan. General Motors Corporation, through its various entities, designed, manufactured, marketed, distributed, and sold Buick, Cadillac, Chevrolet, Oldsmobile, Pontiac, Saturn, and other brand automobiles in the United States and worldwide.

13. In June of 2009, General Motors Corporation ("Old GM") filed for bankruptcy. On July 9, 2009, the United States Bankruptcy Court approved the sale of substantially all of Old GM's assets pursuant to the Agreement, which became effective on July 10, 2009. The Agreement approved the sale of Old GM to Defendant General Motors LLC ("Defendant," "GM," or "New GM").

14. The Agreement defines Defendant's "Purchased Assets" as:

- (xiv) **all books, records, ledgers, files, documents, correspondence, lists, plats, specifications, surveys, drawings, advertising and promotional materials (in whatever form or medium), including Tax books and records and Tax Returns used or held for use in connection with the ownership or operation of the Purchased Assets or Assumed Liabilities, including the Purchased Contracts, customer lists, customer information and account records, computer files, data processing records, employment and personnel records, advertising and marketing data and records, credit records, records relating to suppliers, legal records and information and other data;**
- (xv) **all goodwill and other intangible personal property arising in connection with the ownership, license, use or operation of the Purchased Assets or Assumed Liabilities; . . .**

**Amended and Restated Master Sale and Purchase Agreement at Section 2.2.**

15. Along with the Purchased Assets, GM also expressly took on a range of liabilities. "Liabilities" is defined in the Agreement as "any and all liabilities and obligations of every kind and description whatsoever, whether such liabilities or obligations are known or unknown, disclosed or undisclosed, matured or un-matured, accrued, fixed, absolute, contingent, determined or undeterminable, on or off-balance sheet or otherwise, or due or to become due, including Indebtedness and those arising under any Law, Claim, Order, Contract or otherwise."

16. Among many others, the Liabilities assumed by GM under the Agreement include:

- (vii) (A) all Liabilities arising under express written warranties of Sellers [i.e., old GM] that are specifically identified as warranties and delivered in connection with sale of new, certified used or pre-owned vehicles or new or remanufactured motor vehicle parts and equipment (including service parts, accessories, engines and transmissions) manufactured or sold by Sellers or Purchaser [i.e., New GM] prior to or after the Closing and (B) all obligations under Lemon Laws; . . .
- (viii) all Liabilities to third parties for death, personal injury, or other injury to Persons or damage to property caused by motor vehicles designed for operation on public roadways or by the component parts of such motor vehicles and, in each case, manufactured, sold or delivered by Sellers (collectively, "Product Liabilities"), which arise directly out of accidents, incidents, or other distinct and discreet occurrences that happen on or after the Closing Date and arise from such motor vehicles' operation or performance;....
- (ix) all Liabilities arising out of, relating to, in respect of, or in connection with the use, ownership or sale of the Purchased Assets after the Closing; . . .

17. GM also assumed responsibility for compliance with a wide range of laws and other regulations, including:

- (a) *From and after the Closing, Purchaser [Defendant GM] shall comply with the certification, reporting, and recall requirements of the National Traffic and Motor Vehicle Safety Act, the Transportation Recall Enhancement, Accountability and Documentation Act, the Clean Air Act, the California Health and Safety Code and similar Laws, in each case, to the extent applicable in respect of vehicles and vehicle parts manufactured or distributed by Seller [Old GM].*
- (b) *From and after the Closing, Purchaser [Defendant GM] shall be responsible for the administration, management and payment of all Liabilities arising under (i) express written warranties of Sellers [Old GM] . . . (ii) Lemon Laws.*

18. Moreover, the Bankruptcy Court order approving the Agreement made clear that Defendant GM assumed "the warranty and recall obligations of both Old GM and [Defendant GM]."

19. Pursuant to the Agreement and other orders of the Bankruptcy Court, Defendant GM emerged out of bankruptcy and continued the business of Old GM with many, if not most, of Old GM's employees and, on information and belief, with most of the same senior-level management, officers, and directors.

20. The allegations pertaining to Old GM above are included for purposes of background and context, and to set forth the scope of Defendant GM's liabilities and responsibilities under the Agreement. This Complaint does not assert any causes of action against Old GM; all causes of action and attributions of liability are directed solely against Defendant General Motors LLC.

21. At all times relevant to the claims in this lawsuit, Old GM and New GM were in the business of developing, manufacturing, and marketing cars throughout the United States generally, and specifically in each of the states of citizenship identified in Exhibit "A." New GM has a network of authorized retailers that sell its vehicles and parts throughout the United States.

#### **IV. JURISDICTION**

22. Jurisdiction is proper in this Court pursuant to Case Management Order No. 8 in *In re General Motors LLC Ignition Switch Litigation*, [14-MC-2543, Dkt. No. 36]. Plaintiffs' filing of this Complaint in this district does not alter the choice-of-law analysis and does not constitute a waiver of any of Plaintiffs' rights to transfer to another district at the conclusion of pretrial proceedings in this case. Named Plaintiffs have filed this Complaint in this district in order to advance the efficient and orderly resolution of claims arising from Defendant's conduct and its attendant nationwide devastating effects. At the conclusion of pretrial proceedings in this case, each Named Plaintiff will be entitled to transfer his or her claim to the state of his or her residence as listed on the attached Exhibit "A."

23. This Court has diversity jurisdiction over this action under 28 U.S.C. § 1332(a) because the amount in controversy exceeds \$75,000.00 and Named Plaintiffs are citizens of different states than Defendant.

#### **V. FACTUAL BACKGROUND**

##### ***A. General Background***

24. An auto manufacturer should never make profits more important than safety and should never conceal from consumers or the public any defects that exist in its vehicles. New GM's Vehicle Safety Chief, Jeff Boyer, recently proclaimed that: "Nothing is more important than the safety of our customers in the vehicles they drive." GM Announces New Vehicle Safety Chief, <http://democrats.energycommerce.house.gov/sites/default/files/documents/Testimony-Barra-GM-Ignition-Switch-Recall-2014-4-1.pdf>. Yet, New GM failed to live up to this commitment. Appropriately, the Old GM engineer who designed the ignition switch called it "the switch from hell." Valukas Report at p. 5

25. The first priority of a car manufacturer should be to ensure that its vehicles are safe,



and particularly that its vehicles have operable ignition systems, airbags, power- steering, power brakes, and other safety features that can prevent or minimize the threat of death or serious bodily harm in a collision. In addition, a car manufacturer must take all reasonable steps to ensure that, once a vehicle is running, it operates safely and its critical safety systems (such as engine control, braking, and airbag systems) work properly until such time as the driver shuts down the vehicle. Moreover, a manufacturer that is aware of dangerous design defects that cause its vehicles to shut down during operation, or its airbags not to deploy, must promptly disclose and remedy such defects.

26. To date, GM has sold at least 15 million automobiles installed with defective ignition switches which slip into the “accessory” or “off” position. This turns off the engine as well as the car’s vital engine systems without warning while the car is in motion. The ignition switch defect disables the power steering and power brakes and prevents the deployment of airbags in these vehicles.

## **B. GM Fraudulently Concealed the Ignition Switch Defect**

### ***1. The Defective Vehicles Manufactured by Old and New GM***

27. On February 7, 2014, GM conducted a safety related recall for its 2005-2007 Chevrolet Cobalt and its 2007 Pontiac G5. In these vehicles, the weight on the key ring and/or road conditions or some other jarring event may cause the ignition switch to move out of the run position, turning off the engine. If the key is not in the run position, the air bags may not deploy if the vehicle is involved in a crash, increasing the risk of injury to the vehicle occupants.

28. On February 25, 2014, GM expanded its initial recall to include the 2006-2007 Chevrolet HHR, 2006-2007 Pontiac Solstice, 2003-2007 Saturn Ion, and 2007 Saturn Sky for the same ignition switch defect.

29. On March 28, 2014, GM again expanded its recall to include the 2008-2010 Chevrolet Cobalt, 2008-2011 Chevrolet HHR, 2008-2010 Pontiac G5, 2008-2010 Pontiac Solstice, and 2008-2010 Saturn Sky for the same ignition switch defect.

30. Indeed, throughout the rest of 2014, GM conducted multiple safety recalls for millions of other GM vehicles due to the same ignition switch defect. The design of the ignition switch and related components of these other vehicles are substantially similar to the prior recalled vehicles in the first three months of 2014. As used in this Complaint, these “Subject Vehicles” refer to GM vehicles sold in the United States equipped at the time of sale with an ignition switch sharing a common, uniform, and defective design.

The Subject Vehicles include the following makes and model years:

**2010-2014 Chevrolet Camaro;  
2005-2010 Pontiac G5;**

**1997-2005 Chevrolet Malibu Classic;  
2000-2005 Chevrolet Impala;**

<b>2005-2009 Buick LaCrosse;</b>	<b>2000-2005 Chevrolet Monte Carlo;</b>
<b>2006-2011 Buick Lucerne;</b>	<b>2000-2005 Pontiac Grand Am;</b>
<b>2000-2005 Cadillac Deville;</b>	<b>2004-2008 Pontiac Grand Prix;</b>
<b>2006-2011 Cadillac DTS;</b>	<b>1998-2002 Oldsmobile Intrigue; and</b>
<b>2006-2014 Chevrolet Impala;</b>	<b>1999-2004 Oldsmobile Alero.</b>
<b>2006-2007 Chevrolet Monte Carlo;</b>	<b>2003-2014 Cadillac CTS; Cadillac SRX;</b>

31. Named Plaintiffs' vehicles fall within this group of Subject Vehicles.

32. The ignition switches in the Subject Vehicles contain several common switch points, including "run" (or "on"), "off," and "accessory." At the "run" position, the vehicle's motor engine is running and electrical systems have been activated; at the "accessory" position the motor is off, and electrical power is generally only supplied to the vehicle's entertainment system; and at the "off" position, both the vehicle's engine and electrical systems are turned off. In most vehicles, a driver must intentionally and manually turn the key in the ignition to move to these various positions.

33. In the Subject Vehicles, a detent plunger in the ignition switch does not generate sufficient torque to keep the detent plunger component in position. Thus, when the vehicle and/or ignition is jarred or any additional weight is added to the key ring, the detent plunger can move, switching the ignition from the "run" position to the "accessory" or "off" position.

34. In addition, the Subject Vehicles contain a uniformly designed ignition cylinder, with the key position of the lock module on the steering column and an ignition key with a slot for a key ring at the top. By design, the ignition switch was placed low on the steering column, making it easy for a driver of regular height to inadvertently impact the ignition switch with his or her knee while operating the vehicle. Such an impact may jar the ignition switch and cause it to move from the "run" to the "accessory" or "off" position.

35. The ignition switch on the Subject Vehicles is prone to fail during ordinary and foreseeable driving situations (such as traveling across bumpy or uneven roadways). When the ignition switch "fails," and the ignition switch moves from the "run" to the "accessory" or "off" position during ordinary operation of the vehicle, the power to the vehicle is terminated (even at highway speeds), and the vehicle loses power steering and power brakes, among other things.

36. Each of the Subject Vehicles also contains a uniformly designed airbag system that is disabled when the ignition switch on the vehicles fails during ordinary and foreseeable driving situations. Thus, as a result of the defective design of the Subject Vehicles, a driver whose ignition switch fails may suddenly and without warning experience a vehicular power failure that also disables the vehicle's airbags, steering, and brakes. Such a failure may occur unexpectedly and during normal operation of the vehicle.



37. The Named Plaintiffs purchased Subject Vehicles which contained the defective ignition switch and airbag system described in this Complaint.

38. The ignition switch defect precludes drivers and owners of the Subject Vehicles from proper and safe use of their vehicles, reduces vehicle occupant protection, and endangers Subject Vehicle occupants as well as those in vehicles around them. Further, because GM concealed the existence of the ignition switch defect, no driver or owner of the Subject Vehicles knew about, or could reasonably have discovered, the ignition switch defect.

***2. GM Learned of the Ignition Switch Defect Shortly After the Bankruptcy Sale, but Concealed the Defect for Years***

39. In 2009, Old GM declared bankruptcy in the United States Bankruptcy Court in the Southern District of New York.

40. On July 9, 2009, the United States Bankruptcy Court approved the sale of Old GM, which was converted into Defendant New GM. From its inception, New GM, which retained the vast majority of Old GM's senior and management level executives and engineers, knew that its predecessor had manufactured and sold millions of vehicles afflicted with the ignition switch defect. Some of the Old GM employees retained by New GM include current CEO Mary T. Barra; designer of the ignition switch and engineer Ray DeGiorgio; director of product investigations Carmen Benavides; engineer Gary Altman; engineer Jim Federico; vice presidents for product safety John Calabrese and Alicia Boler- Davis; vice president of regulatory affairs Michael Robinson; director of product investigations Gay Kent; general counsel and vice president Michael P. Milliken; and in-house product liability lawyer William Kemp.

41. On or around the day of its formation as an entity, New GM also acquired, inter alia, the knowledge of the contents of Old GM's "files" and company "documents." To that end, New GM acquired notice of the safety-related defects contained in Old GM's files, including numerous engineering reports, investigative reports, failure analyses, technical service bulletins, and other documentation concerning the defective ignition switch and airbag system described herein.

***a. New GM Learns of the Ignition Switch Defect***

42. From the day of its formation as a corporate entity, New GM acquired notice and full knowledge of the following:

- a. In 2001, during pre-production testing of the 2003 Saturn Ion, Old GM engineers learned that the vehicle's ignition switch could unintentionally move from the "run" to the "accessory" or "off" position. Old GM further

learned that when the ignition switch moved from “run” to the “accessory” or “off” position, the vehicle’s engine would stall and/or lose power. In a section of an internal report titled, “Root Cause Summary,” Old GM engineers identified two “causes of failure,” namely: “[l]ow contact force and low detent plunger force.”

- b. Delphi Automotive PLC (“Delphi”), the manufacturer of the ignition switches, informed Old GM that the ignition switch did not meet Old GM’s torque specifications. The ignition switch “was developed as a ‘corporate common’ part, meaning that it was designed to be used in multiple vehicle platforms.” Report to Board of Directors of General Motors Company Regarding Ignition Switch Recalls at p. 19 (May 29, 2014) (hereinafter, “Valukas Report”). The defective ignition switches were installed in, inter alia, the Chevrolet HHR, Chevrolet Cobalt, Saturn Ion, Saturn Sky, Pontiac G5, and Pontiac Solstice. *Id.* at 18-19. The use of common ignition switches across vehicle platforms was a method to reduce costs. *Id.* The Design Release Engineer for the Ion ignition switch, Ray DeGiorgio, specifically discussed with Delphi the fact that the switches did not meet the torque required by Old GM’s specifications.
- c. DeGiorgio also corresponded with representatives of Koyo, the supplier of the Ion steering column into which the ignition switch was to be installed. In his correspondence, DeGiorgio stated that ten of twelve prototype ignition switches recently provided by Delphi “[f]ailed to meet engineering requirements,” and remarked that the “failure is significant.”
- d. Nonetheless, rather than delay production of the Saturn Ion, and redesign the ignition switch in order to ensure that it met Old GM’s specifications, Mr. DeGiorgio went ahead and approved use of ignition switches he knew did not meet Old GM’s design specifications.
- e. Old GM contracted with Continental Automotive Systems US, Inc. (“Continental”) to manufacture the airbag system, including the sensing system, in the Subject Vehicles, including the 2003 Saturn Ion.
- f. The airbag system in the Subject Vehicles was defectively designed so that it would shut off and the airbags would not deploy when the key in the ignition turned from the “run” to the “accessory/off” position during foreseeable driving operation.
- g. In 2002, Old GM began manufacturing and selling 2003 Saturn Ions with the defective ignition switches and defective airbag systems.
- h. As far back as 2003, Old GM received a complaint of a stalling Pontiac Grand Am and engineering changes were ultimately made to increase the turning force required in the ignition switch for that car, according to one July 16, 2004 letter from GM to regulators.

- i. The 2004 letter also showed similar actions being taken for some Chevrolet Malibu and Oldsmobile Alero models. While the part number was changed in those cases, the old part number was designated as “use,” making it possible that the faulty switch was used to fix other vehicles, GM said.
- j. In 2004, an engineering change was made to the Pontiac Grand Prix ignition switch to be consistent with the Malibu and Alero changes. GM did not change the Grand Prix ignition switch’s part number.
- k. In 2004, Old GM engineers reported that the ignition switch on the Saturn Ion was so weak and placed so low on the steering column that the driver’s knee could easily bump the key and turn off the vehicle.
- l. This defect was sufficiently serious that an Old GM engineer, Gerald A. Young, reported in January 2004 that “[t]he ignition switch is too low. All other keys and the key fob hit on the driver’s right knee. The switch should be raised at least one inch toward the wiper stalk.” Young then concluded that “[t]his is a basic design flaw and should be corrected if we want repeat sales.”
- m. Mr. Young was not alone in his observations. In a February 19, 2004 report concerning his model year 2004 Saturn Ion, Old GM employee Onassis Matthews stated, “The location of the ignition key was in the general location where my knee would rest (I am 6’ 3” tall, not many places to put my knee). On several occasions, I inadvertently turn [sic] the ignition key off while driving down the road. For a tall person, the location of the ignition key should be moved to a place that will not be inadvertently switched to the off position.”
- n. Two months later, in an April 15, 2004 report concerning his model year 2004 Saturn Ion, Old GM employee Raymond P. Smith described a moving stall: “I thought that my knee had inadvertently turned the key to the off position.”
- o. Meanwhile, a July 1, 2004 report by Siemens VDO Automotive analyzed the relationship between the ignition switch in Old GM-branded vehicles and the airbag system. The Siemens report concluded that when an Old GM-branded vehicle experienced a power failure, the airbag sensors were disabled. The Siemens report was distributed to at least five Old GM engineers.
- p. The Chevrolet Cobalt was in pre-production at this time. In spite of the problems reported with the Saturn Ion’s switch, Old GM installed the same ignition switch and airbag system in the 2005 Cobalt as it had in the Ion.
- q. Unsurprisingly, reports of moving stalls surfaced almost immediately around the time of the Cobalt’s production launch in 2004. At a press event in the summer or fall of 2004, a journalist informed Doug Parks, the Cobalt Chief Engineer, that while adjusting his seat in the Cobalt he was test driving, the journalist had inadvertently turned off the car by hitting his knee against the key fob or chain.

Parks asked Gary Altman, the Program Engineering Manager, to follow up on the complaint by trying to replicate the incident and to determine a fix. Altman thereafter replicated the incident at an Old GM testing facility.

- r. Mr. DeGiorgio learned about the moving stall at the press event in 2004 and was approached by an Old GM engineer who suggested that Old GM should “beef up” the ignition switch detents. DeGiorgio rejected this idea.
- s. Around this same time, Old GM opened an engineering inquiry known as a Problem Resolution Tracking System (PRTS) to address the complaint from the press event that a Cobalt could be “keyed off with knee while driving.” At this time, PRTS issues were analyzed by a Current Production Improvement Team (CPIT). The CPIT that examined the Cobalt issue beginning in November 2004 included a cross-section of business people and engineers, including Gary Altman and Lori Queen, Vehicle Line Executive on the case.
- t. Old GM considered a number of potential solutions to the problem during the PRTS, including changes to the key position on the lock module and measures to increase the torque in the ignition switch. Indeed, the CPIT characterized a suggestion to change the location of the ignition switch on the steering column from a low-mount to a higher mount as a “sure solution,” but rejected it because it was too expensive. Old GM also considered changing the key from a slot to a hole configuration.
- u. Changing the key from a slot to a hole configuration would reduce the lever arm of the key and key chain. With the slot design, the key hangs lower on the key chain, which increases the torque force on the ignition switch when the chain is contacted or moved in any way. Old GM engineers determined that changing the key to a hole configuration would lessen the consequences of impacts on the key and significantly reduce the chance that the key would inadvertently move from the “run” to the “accessory/off” position during ordinary driving maneuvers.
- v. Old GM engineer David Thrush determined that redesigning the key to a hole design would have cost less than one dollar per vehicle.
- w. In the end, however, Old GM engineers and executives decided to do nothing. In March of 2005, Mr. Altman, who was the Cobalt Program Engineering Manager, issued a directive to close the November 2004 PRTS with no action. The rationale of Old GM’s decision makers was that the “lead-time for all solutions is too long” and the “tooling cost and piece price are too high.” Thus, “none of the solutions represents an acceptable business case”—a standard phrase used by Old GM when closing a PRTS without action due to cost. David Thrush, the Design Release Engineer for the Cobalt ignition cylinder, explained that an “acceptable business case” is one whose solution should solve the issue, be cost effective, and have an acceptable lead time to implement the change. But one of the very solutions proposed by Thrush— changing the ignition key from a slot to a hole

configuration—would have cost less than one dollar per vehicle.

- x. Not only did Old GM close the PRTS with no action, it also downplayed the severity of the safety threat posed, rating the specter of a moving stall (even at highway speeds) with a severity level of 3—on a scale of 1 (most severe) to 4 (least severe).
- y. On February 28, 2005, Old GM issued a bulletin to its dealers regarding engine-stalling incidents in 2005 Chevrolet Cobalts and 2005 Pontiac Pursuits (the Canadian version of the Pontiac G5).
- z. In the February 28, 2005 bulletin, Old GM provided the following recommendations and/or instructions to its dealers—but did not provide this information to the public in general:

There is potential for the driver to inadvertently turn off the ignition due to low key ignition cylinder torque/effort. The concern is more likely to occur if the driver is short and has a large heavy key chain

In the cases this condition was documented, the driver's knee would contact the key chain while the vehicle was turning. The steering column was adjusted all the way down. This is more likely to happen to a person that is short as they will have the seat positioned closer to the steering column.

In cases that fit this profile, question the customer thoroughly to determine if this may be the cause. The customer should be advised of this potential and to take steps, such as removing unessential items from their key chains, to prevent it.

Please follow this diagnosis process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

- aa. At this time, Old GM knew that drivers were inadvertently turning off the vehicles due to design defects in the ignition switches installed in those vehicles, and not only because “short” drivers were impacting the steering column or because drivers’ key chains were “heavy.”
- bb. Old GM failed to disclose and, in fact, concealed the February 28, 2005 bulletin, as well as the information contained therein, to Cobalt and Pursuit owners/lessees, and sent affirmative representations to dealers that did not accurately describe the nature of the problem, the multiple design steps needed for a solution to the problem, and Old GM’s knowledge of the problem.
- cc. Indeed, rather than disclosing this serious safety problem that uniformly affected all Chevrolet Cobalts, Old GM instead concealed and obscured the defect-related

problems, electing to wait until customers brought their cars to a dealership after an engine-stalling incident had occurred. Further, Old GM offered even its own dealers an incomplete, incorrect, and insufficient description of the defects and the manner in which to actually remedy them.

- dd. As of February 2005, Old GM engineers knew that the Chevrolet Cobalt ignition switches were defectively designed as discussed in this Complaint.
- ee. Pursuant to 49 C.F.R. § 573.6, which requires an automobile manufacturer to “furnish a report to the NHTSA for each defect . . . related to motor vehicle safety,” Old GM had a duty to disclose the safety-related defects in the Chevrolet Cobalt and all other Subject Vehicles as soon as it knew of them.
- ff. Instead of complying with its legal obligations, however, Old GM fraudulently concealed the ignition switch defect from the public and continued to manufacture and sell the Subject Vehicles with known safety defects.
- gg. Between February 2005 and December 2005, Old GM continued to receive reports of moving stalls and/or power failures in the Subject Vehicles. Indeed, Old GM opened multiple PRTS inquiries during this time period regarding reports of power failure and/or engine shutdown in Subject Vehicles.
- hh. As part of one such PRTS, Quality Brand Manager Steven Oakley asked William Chase, an Old GM warranty engineer, to estimate the warranty impact of the ignition switch defect in the Cobalt vehicles. Chase estimated that for Cobalt vehicles on the road for 26 months, 12.40 out of every 1,000 vehicles would experience inadvertent power failure while driving. Old GM did not provide this information to its dealers, to regulators, or to the general public.
- ii. In a recently released internal email from 2005, GM Engineer Laura Andres told her GM colleagues that a 2006 Chevrolet Impala shut down when she hit a pothole, in what a technician described as a switch issue. She wrote, “I think this is a serious safety problem, especially if this switch is on multiple programs. I’m thinking big recall.”
- jj. In May 2005, a customer demanded that Old GM repurchase his Cobalt. The complainant stated that the ignition switch shut off during normal driving conditions with no apparent contact between the driver’s knee and key chain or fob. Steven Oakley forwarded this information internally, stating that the ignition switch “goes to the off position too easily, shutting the car off.” Oakley’s email was forwarded to DeGiorgio.
- kk. The problem with moving stalls began to receive increased press attention in May and June of 2005. On May 26, 2005, a writer for the Sunbury Daily Item in Pennsylvania reviewed the Cobalt and reported that “[u]nplanned engine shutdowns happened four times during a hard-driving test last week. . . . I never



encountered anything like this in 37 years of driving and I hope I never do again.” Similarly, a writer for the New York Times reported that his wife experienced a moving power failure while driving a Cobalt.

- ll. At or around the late spring of 2005, Old GM, through Product Safety Communications Manager Alan Adler (who now works for New GM), issued the following statement regarding customer-reported engine-stalling events in the Chevrolet Cobalt:

In rare cases when a combination of factors is present, a Chevrolet Cobalt driver can cut power to the engine by inadvertently bumping the ignition key to the accessory or off position while the car is running.

When this happens the Cobalt is still controllable. The engine can be restarted after shifting to neutral.

GM has analyzed this condition and believes it may occur when a driver overloads a key ring, or when the driver’s leg moves amid factors such as steering column position, seat height and placement. Depending on these factors, a driver can unintentionally turn the vehicle off.

Service advisers are telling customers they can virtually eliminate this possibility by taking several steps, including removing non-essential material from their key rings. Ignition systems are designed to have “on” and “off” positions, and practically any vehicle can have power to a running engine cut off by inadvertently bumping the ignition from the run to the accessory or off position. Old GM’s statement was demonstrably misleading and false.

- mm. Further, Old GM’s above-referenced statement was demonstrably false and misleading because Old GM knew that safety incidents related to the ignition switches were the result of the safety-related defects identified in the November 2004 PRTS.
- nn. The negative media coverage, however, was becoming concerning. As a result, Old GM tasked its Product Investigations unit to examine the ignition switch defect. The Product Investigations unit typically was charged with solving significant engineering problems, both of customer satisfaction and product safety. Product Investigations Manager Doug Wachtel and his team examined early data from the field and found 14 incidents related to the ignition switch. Wachtel and company also tried to recreate moving stalls themselves. In this vein, Wachtel and Gay Kent drove a Cobalt around Old GM’s property in Warren, Michigan. Ms. Kent had a long and heavy key chain, and was able to knock the ignition from “run” to “accessory” simply by moving her leg so that her jeans caused friction against the fob.
- oo. The Product Investigations unit, in spite of its findings, concluded that the

ignition switch problem was not of sufficient seriousness to warrant a recall. At this time, Old GM knew that a defect existed in its vehicles, but it downplayed and denied the magnitude of the problem, and did nothing to disclose the issue to its customers.

- pp. The failure to act did not end here. Around June 7, 2005, DeGiorgio was asked to propose a change to the ignition switch that would double the torque required to turn the switch. DeGiorgio identified two possibilities. First, he proposed using a switch under development for the Saturn Vue and the Chevrolet Equinox (the “GMT 191”). Because the GMT 191 switch was superior to the current ignition switch both electrically and mechanically, DeGiorgio referred to it as the “gold standard of ignition switches.” Second, DeGiorgio proposed redesigning the ignition switch already in use. Part of DeGiorgio’s plan for this latter option included adding a second detent plunger.
- qq. On June 14, 2005, Old GM’s Vehicle and Process Integration Review (VAPIR) team for the Cobalt met to discuss potential solutions to the moving stall issue. Proposed solutions were categorized as either “short-term” or “long-term.” As a proposed short-term solution, Old GM engineers proposed using a smaller key ring and replacing the slotted key head with one that contained a hole. (This was the same solution proposed by David Thrush during the November 2004 PRTS.) Old GM’s long-term solution centered on DeGiorgio’s proposal to replace the ignition switch with the GMT 191, or “gold standard” switch. The GMT 191 would allegedly double the torque required to turn the ignition. Old GM engineers proposed to implement the new switch beginning with model year 2007 or 2008 vehicles at a cost of just \$1.00 per vehicle, plus tooling costs.
- rr. Shortly after its June 14, 2005 meeting, the Cobalt VAPIR team approved a “fix” for existing customers that would address the slotted key heads: a plug capable of insertion into the key head to eliminate the slot along the head of the key. The VAPIR team also approved a redesign of keys for future model year vehicles to eliminate the slot design (a change that was not implemented). Old GM then issued a Preliminary Information to its dealers, explaining that the key insert was available for 2005 Chevrolet Cobalt vehicles. The key insert solution did not, however, address the core problem of low torque and the low placement of the ignition switch on the steering cylinder. Indeed, Old GM’s engineers regarded the key head design change as only a temporary solution— or, as one Old GM engineer described it, a “band-aid.” Old GM’s failure to take decisive action to address the defect would soon prove fatal.
- ss. On June 29, 2005, an Old GM customer filed the following complaint (and succinctly identified the safety risk) regarding a 2005 Cobalt and its tendency to lose power during ordinary driving scenarios:

Dear Customer Service:

This is a safety recall issue if ever there was one. . . . The problem is the ignition turn switch is poorly installed. Even with the slightest touch, the car will shut off while in motion. I don't have to list to you the safety problems that may happen, besides an accident or death, a car turning off while doing a high speed . . .

tt. Just weeks later, in July of 2005, Old GM received notice that Amber Marie Rose, a 16 year old resident of Clinton, Maryland, was killed in an accident after her 2005 Chevrolet Cobalt drove off the road and struck a tree head-on. The airbags in Ms. Rose's Cobalt did not deploy during this frontal collision. NHTSA opened an investigation and hired Calspan Crash Data Research to conduct a Special Crash Investigation (SCI). The SCI determined that the ignition switch in Ms. Rose's Cobalt was in the "accessory" position at the time of collision. Upon information and belief, Old GM subsequently entered into a confidential settlement agreement with Ms. Rose's mother.

uu. In December 2005, Old GM issued a Technical Service Bulletin (05-02- 35-007) (the "TSB"). The TSB applied to 2005-2006 Chevrolet Cobalts, 2006 Chevrolet HHRs, 2005-2006 Pontiac G5, 2006 Pontiac Solstices, and 2003-2006 Saturn Ions, all of which contained uniformly designed defective ignition switches. The TSB, which was issued only to Old GM dealers, was captioned, "Information on Inadvertent Turning of Key Cylinder, Loss of Electrical System and No DTCs." The TSB stated:

There is potential for the driver to inadvertently turn off the ignition due to low ignition key cylinder torque/effort.

The concern is more likely to occur if the driver is short and has a large and/or heavy key chain. In these cases, this condition was documented and the driver's knee would contact the key chain while the vehicle was turning and the steering column was adjusted all the way down. This is more likely to happen to a person who is short, as they have the seat positioned closer to the steering column. In cases that fit this profile, question the customer thoroughly to determine if this may be the cause. The customer should be advised of this potential and should take steps to prevent it—such as removing unessential items from their key chain. . . .

vv. As with its prior bulletin regarding the Subject Vehicles, the information. Old GM provided in the TSB was false and misleading.

ww. For example, the TSB intentionally omitted use of the word "stall," which was language Old GM knew was a red flag to regulators. Old GM Quality Service Manager Steven Oakley, who drafted the December 2005 TSB, stated that the term "stall" is a "hot" word that Old GM did not use in TSBs because it may raise a concern about vehicle safety and thereby suggest that a recall, not a TSB, is

appropriate. Old GM personnel also stated that “there was concern about the use of ‘stall’ in a TSB because such language might draw the attention of NHTSA.” Valukas Report at 93 & 392. Rather than describe the defective condition accurately, Old GM used language to obfuscate the problem at hand.

- xx. Further, the TSB fails to mention that an ignition switch that turns to the “accessory” or “off” position will disable the airbags, cut the engine, and disable power steering and brakes.
- yy. At the time it issued the TSB, Old GM knew that power failure incidents were happening to drivers of all heights and sizes, and to drivers with no extra items on their key chains.
- zz. Between November 2005 and March 2006, Old GM learned of at least three incidents in which operators of Chevrolet Cobalt vehicles lost control of the vehicle and experienced front-end collisions in which the airbags of the vehicle failed to deploy. In two of these incidents, data obtained from the vehicle’s Sensory Diagnostic Module (SDM) showed that the vehicle was in the “accessory” position just before impact. Old GM opened internal investigations into each of these three incidents but generally did nothing.
- aaa. On April 24, 2006, Ray DeGiorgio approved plans to redesign the ignition switch in order to improve the switch’s torque performance. The redesign plan, inter alia, included a new detent plunger and spring in the detent plunger.
- bbb. In spite of this redesign, Old GM did not issue a corresponding change of the ignition switch’s part number. Upon information and belief, Old GM neglected to change the part number in an effort to conceal its redesign of the ignition switch. Government regulators would later explain that this action—concealing the part change by applying the same part number to the redesigned ignition switches—prevented NHTSA from discovering the ignition switch defect for years.
- ccc. Indeed, New GM CEO Mary Barra acknowledged in April 2014 that the failure to change the part number for the ignition switches was inappropriate and did not meet industry standard behavior.
- ddd. Furthermore, and in spite of the redesign, the ignition switches continued to fall short of Old GM’s design specifications for torque performance. The redesigned ignition switches therefore continued to be defective as designed and manufactured.
- eee. In October 2006, Old GM again updated the TSB (05-02-35-007) to include additional model years: the 2007 Saturn Ion and Sky, 2007 Chevrolet HHR, 2007 Chevrolet Cobalt, and 2007 Pontiac Solstice and G5. These model year vehicles possessed the same safety-related defects as the vehicles included in the original

TSB.

fff. In August 2007, Old GM met with Continental to review the SDM data from a crash of a 2005 Chevrolet Cobalt where the airbags failed to deploy, resulting in a fatal injury. By this time, Continental had knowledge of the safety-related defects discussed in this Complaint. Neither Old GM nor Continental shared the results of this meeting with relevant regulatory authorities or the public.

ggg. The next month, the Chief of the Defect Assessment Division within the Office of Defects Investigation of NHTSA proposed that the agency investigate “frontal airbag non-deployment in 2003-2006 Chevrolet Cobalt/Saturn Ion.” The proposal was prompted by a “pattern of reported non-deployments” that were “first observed in early 2005.” According to the Chief of the Defect Assessment Division, and in response to inquiries from NHTSA, GM “indicat[ed] that they see no specific pattern.”

hhh. At this time, Old GM knew of the problems related to airbag non deployment in the Chevrolet Cobalt vehicles and, according to this email, was deliberately misleading NHTSA about its knowledge of these problems. Old GM knew, for example, that its airbag systems would become disabled when the ignition switch to a vehicle moved from the “run” position to the “accessory” or “off” position during normal operation of the vehicle. All the while, however, Old GM also knew that NHTSA believed that in most vehicles, if not all, the airbag systems were operable for several seconds following a power loss. Thus, Old GM knew that NHTSA was mistaken and did nothing to correct NHTSA’s mistaken belief.

iii. What is more, between December 2006 and October 2007, Old GM learned of at least five fatal accident involving frontal collisions in Subject Vehicles wherein the airbags failed to deploy.

jjj. The Acting Administrator of NHTSA, David Friedman, testified in 2014 that Old GM withheld data from NHTSA regarding the likelihood of airbag non-deployment in the Subject Vehicles during this time period. Old GM withheld this data in an effort to thwart any investigation by NHTSA and to avoid a recall of the Subject Vehicles.

kkk. Old GM’s concealment and obfuscation was not limited to its dealing with NHTSA. In a 2008 internal presentation, Old GM instructed its employees to avoid using the following “judgment” words:

always	annihilate	apocalyptic	asphyxiating	bad
--------	------------	-------------	--------------	-----

Band-Aid	big time	brakes like an "X" car	cataclysmic	catastrophic
Challenger	chaotic	Cobain	Condemns	evicscerated [sic]
Corvair-like	crippling	critical	dangerous	deathtrap
debilitating	decapitating	defect	defective	detonate
Dis-emboweling	enfeebling	evil	ghastly	explode

failed	flawed	genocide	rolling sarcophagus	grenade-like
grisly	gruesome	Hindenburg	hobbling	horrific
impaling	inferno	Kevorkianesque	lacerating	life-threatening
maiming	mangling	maniacal	never	potentially-disfiguring
power [sic]	keg	problem	safety	safety related



serious	spontaneous combustion	startling	suffocating	suicidal
terrifying	Titanic	tomblike	unstable	widow-maker

- lll. Instead of using commonsense language, Old GM employees were advised in Orwellian fashion to use specific words to avoid disclosure of the material safety risks associated with Old GM products, and in so doing furthered the cover-up and fraud through intentional (and misleading) word substitutions, such as:

“Issue, Condition [or] Matter” instead of “Problem”

“Has Potential Safety Implications” instead of “Safety”

“Does not perform to design” instead of “Defect/Defective”

mmm. Old GM knew its defective vehicles were killing and/or maiming its customers, but it nonetheless instructed its employees to avoid words like “defect” or “safety”—words that accurately described the issues. Instead of publicly admitting the dangerous safety defects in its vehicles, Old GM repeatedly blamed accidents on driver error.

- nnn. Upon information and belief, Old GM’s policy against “judgment” words, and linguistic obfuscation in general, was adopted and continued on by New GM after the bankruptcy sale.

- ooo. New GM Continues to Fraudulently Conceal the Ignition Switch Defect After the Bankruptcy Sale.

43. New GM continued its business with full knowledge of Old GM’s awareness and concealment of the defects with the ignition switch and airbag system, and with knowledge of Old GM’s failure to disclose those defects to the public- or, for that matter, to the Bankruptcy Court. Had New GM acted when it acquired knowledge of the ignition switch defect, Named Plaintiffs would likely not have been involved in an accident.

44. Rather than promptly recalling the Subject Vehicles, however, New GM fraudulently concealed the existence of the safety defects in the Subject Vehicles. Moreover, New GM continued to manufacture vehicles with the ignition switch defect after it emerged from

bankruptcy. Indeed, hundreds of thousands of the vehicles manufactured by New GM have since been recalled for defective ignition switches.

45. In March 2010, GM recalled nearly 1.1 million Cobalt and Pontiac G5 models for faulty power steering issues. In recalling these vehicles, GM recognized that loss of power steering, standing alone, was grounds for a safety recall. Yet, incredibly, GM claims it did not view the ignition switch defect (which disables power steering as well as other functions) as a “safety issue,” but only a “customer convenience issue.” Despite its knowledge of the ignition switch defect, GM did not include the ignition switch defect in this recall. Further, although the Chevrolet HHR used the same steering system as the Cobalt and Pontiac G5 (and had the same ignition switch defect), GM did not recall any Chevrolet HHR vehicles at this time.

46. Just days after the power steering recall, GM’s deadly ignition switch took another life. On March 10, 2010, Brooke Melton was driving her 2005 Chevrolet Cobalt on a two-lane highway in Paulding County, Georgia. While she was driving, her key turned from the “run” to the “accessory/off” position causing her engine to shut off. After her engine shut off, she lost control of her Cobalt, which traveled into an oncoming traffic lane, where it collided with an oncoming car. Ms. Melton was killed in the crash. And the deaths did not stop here.

47. On December 31, 2010, in Rutherford County, Tennessee, a 2006 Cobalt traveled off the road and struck a tree. Although there was a frontal impact in this incident, the front airbags failed to deploy. The download of the SDM later showed the key was in the “accessory/off” position at the time of the crash. GM received notice of this incident, opened a file, and referred to it as the “Chansuthus” incident.

48. Also on December 31, 2010, in Harlingen, Texas, a 2006 Cobalt traveled off the road and struck a curb. Although there was a frontal impact, the front airbags failed to deploy. GM received notice of this incident, opened a file, and referred to it as the “Najera” incident.

49. On March 22, 2011, Ryan Jahr, a GM engineer, downloaded the SDM from Brooke Melton’s Cobalt. The information from the SDM download showed that the key in the Cobalt turned from the “run” to the “accessory/off” position 3-4 seconds before the crash. On June 24, 2011, Brooke Melton’s parents filed a lawsuit against GM.

50. In August 2011, GM assigned Engineering Group Manager Brian Stouffer to assist with a Field Performance Evaluation (FPE) that it had opened to investigate frontal airbag non-deployment incidents in Chevrolet Cobalts and Pontiac G5s.

51. On December 18, 2011, in Parksville, South Carolina, a 2007 Cobalt traveled off the road and struck a tree. Although the vehicle sustained a frontal impact, the front airbags did not deploy. A subsequent download of the SDM showed that the ignition key was in the “accessory/off” position at the time of impact. GM received notice of this incident, opened a file, and referred to it as the “Sullivan” incident.

52. In early 2012, Brian Stouffer asked Jim Federico (who reported directly to Mary Barra at the time) to oversee the FPE investigation into frontal airbag non-deployment incidents. Federico was named the “executive champion” for the investigation to help coordinate resources.

53. In May 2012, GM engineers tested the torque on numerous ignition switches of 2005-2009 Cobalt, 2007-2009 Pontiac G5, 2006-2009 HHR, and 2003-2007 Ion vehicles that were parked in a junkyard. The results of these tests showed that the torque required to turn the ignition switches from the “run” to the “accessory/off” position in most of these vehicles did not meet GM’s minimum torque specification requirements. Even vehicles from model years 2008- 2009, after Ray DeGiorgio approved the redesign of the ignition switch, by and large failed to meet GM’s torque specifications. These results were reported to Stouffer and other members of the FPE.

54. In September 2012, Stouffer requested assistance from a “Red X Team” as part of the FPE investigation. The Red X Team was a group of engineers within GM assigned to find the root cause of the airbag non-deployments in front-end accidents involving Chevrolet Cobalts and Pontiac G5s. By that time, however, it was clear that the root cause of the airbag non- deployments in a majority of the front-end accidents was the defective ignition system.

55. Indeed, Mr. Stouffer acknowledged in his request for assistance that the Chevrolet Cobalt could experience a power failure during an off road event, or if the driver’s knee contacted the key and turned off the ignition. Mr. Stouffer further acknowledged that such a loss of power could cause the airbags not to deploy. In other words, Mr. Stouffer knew full well the reasons for the airbag non-deployments, yet he requested additional assistance in order to stall and/or ignore the problem.

56. At this time, GM did not provide the information that it had developed during the FPE to NHTSA or the public.

57. Under 49 C.F.R. § 573.6, GM had a duty in 2012, when it clearly was aware of the ignition switch defect, to disclose the defect in the Subject Vehicles. Rather than comply with its legal obligations, GM continued to fraudulently conceal this defect from the public and the US government.

58. Had GM complied with its obligations under § 573.6, a recall may have been implemented in 2012.

59. Acting NHTSA Administrator David Friedman recently stated, “at least by 2012, GM staff was very explicit about an unreasonable risk to safety” from the ignition switches in the Subject Vehicles.


60. Mr. Friedman continued: “GM engineers knew about the defect. GM lawyers knew about the defect. But GM did not act to protect Americans from the defect.”

61. There is significant evidence that multiple in-house attorneys knew of and understood the ignition switch defect in and around 2012 and 2013. These attorneys, including in-house lawyer Michael Milliken, negotiated settlement agreements with families whose loved ones had been killed and/or injured while operating a Subject Vehicle under circumstances that implicated the ignition switch defect. In spite of their knowledge of the ignition switch defect, GM's attorneys concealed what they knew and neglected to question whether the Subject Vehicles should be recalled. This quest to keep the ignition switch defect secret prolonged its ultimate discovery and contributed to added death and injury.

62. During the FPE inquiry, GM determined that, although increasing the detent in the ignition switch would reduce the chance that the key would inadvertently move from the "run" to the "accessory/off" position, it would not be a total solution to the problem.

63. Indeed, GM engineers identified several additional ways to actually fix the problem. Unsurprisingly, these solutions echoed solutions that Old GM engineers had proposed years before, but had decided not to implement because of cost concerns. GM engineers proposed adding a shroud to prevent a driver's knee from contacting the key, modifying the key and lock cylinder to orient the key in an upward facing orientation when in the "run" position, and adding a push button to the lock cylinder to prevent it from slipping out of run. GM rejected each of these ideas.

64. The photographs below depict a GM engineer in the driver's seat of a Cobalt during the investigation of Cobalt stalling incidents. Note the proximity of the driver's knee to the ignition key:



These photographs show the dangerous position of the key in the lock module on the steering column, as well as the key with the slotted head, which allows the key fob to hang too low off the steering column. GM engineers understood that the key fob can be impacted and pinched between the driver's knee and the steering column, and that this

may cause the key to inadvertently turn from the “run” to the “accessory” or “off” position. The photographs show why GM engineers understood that increasing the detent in the ignition switch would not be a total solution to the problem, for such a step would not alleviate the possibility of impacting the key with a driver’s knee. The photographs also show why GM engineers believed that additional changes (such as the shroud) were necessary to fully fix the defects with the ignition switch.

65. On October 4, 2012, there was a meeting of the Red X Team during which Jim Federico gave an update of the Cobalt airbag non-deploy investigation. According to an email from Stouffer on the same date, the “primary discussion was on what it would take to keep the SDM active if the ignition key was turned to the accessory mode.” Again, GM engineers recognized that the SDM should remain active if the key is turned to the “accessory/off” mode, but GM took no action at this time to remedy the ignition switch defect or notify customers that the defect existed.

66. During the October 4, 2012 meeting, Stouffer and the other members of the Red X Team also discussed “revising the ignition switch to increase the effort to turn the key from Run to Accessory.”

67. On October 4, 2012, Mr. Stouffer emailed Ray DeGiorgio and asked him to “develop a high level proposal on what it would take to create a new switch for service with higher efforts.” On October 5, 2012, DeGiorgio responded:

Brian,

In order to provide you with a HIGH level proposal, I need to understand what my requirements are. What is the TORQUE that you desire? Without this information I cannot develop a proposal.

68. On October 5, Stouffer responded to DeGiorgio’s email, stating: Ray,

As I said in my original statement, I currently don’t know what the torque value needs to be. Significant work is required to determine the torque. What is requested is a high level understanding of what it would take to create a new switch.

69. DeGiorgio replied to Stouffer the following morning:

Brian,

Not knowing what my requirements are I will take a SWAG at the Torque required for a new switch. Here is my level proposal

*Assumption is 100 N cm Torque.*

- New switch design = Engineering Cost Estimate approx. \$300,000
- Lead Time = 18 – 24 months from issuance of GM Purchase Order and supplier selection.

Let me know if you have any additional questions.

Stouffer later admitted in a deposition that DeGiorgio's reference to "SWAG" was an acronym for "Silly Wild-Ass Guess."

70. DeGiorgio's cavalier attitude exemplifies GM's approach to the safety-related defects that existed in the ignition switch and airbag system in the Subject Vehicles. Rather than seriously addressing the safety-related defects, DeGiorgio's emails show he understood the ignition switches were contributing to the crashes and fatalities, and he could not care less.

71. It is also obvious from this email exchange that Stouffer, who was a leader of the Red X Team, had no problem with DeGiorgio's cavalier and condescending response to the request that he evaluate the redesign of the ignition switches.

72. On April 29, 2013, Ray DeGiorgio was deposed in Detroit, Michigan as part of the lawsuit brought by Brooke Melton's parents. At his deposition, Mr. DeGiorgio was shown photographs of the differences between the ignition switch in Brooke's Cobalt and the ignition switch in the 2008 Cobalt (which DeGiorgio had redesigned without changing the part number).

73. Mr. DeGiorgio was questioned about his knowledge of any differences in the ignition switches:



Q. And I'll ask the same question. You were not aware before today that GM had changed the spring – the spring on the ignition switch had been changed from '05 to the replacement switch?

MR. HOLLADAY: Object to the form. Lack of predicate and foundation. You can answer.

THE WITNESS: I was not aware of a detent plunger switch change. We certainly did not approve a detent plunger design change.

Q. Well, suppliers aren't supposed to make changes such as this without GM's approval, correct?

A. That is correct.

Q. And you are saying that no one at GM, as far as you know, was aware of this before today?

MR. HOLLADAY: Object. Lack of predicate and foundation. You can answer.

THE WITNESS: I am not aware about this change.

**(DeGiorgio Deposition, pp. 151-152).**

74. Mr. DeGiorgio's testimony left no doubt that he unequivocally disclaimed any knowledge of any change in the ignition switch in the 2005-2010 Cobalts. Mr. DeGiorgio, however, authorized the redesign to the ignition switches in 2006. Thus, the testimony provided in 2013 was knowingly false and intended to mislead.

75. Mr. DeGiorgio also provided the following testimony about the ignition switch supplier, Delphi:

Q. And there weren't any changes made – or were there changes made to the switch between '05 and 2010 that would have affected the torque values to move the key from the various positions in the cylinder?

A. There was one change made to the resistor in '08, but that should not have affected the torque or the displacement of the switch.

I can restate this way: There was an electrical change made in '08, but not a mechanical change – at least there were no official changes, mechanical changes, made to the switch that I know of.

Q. When you say no official, could there be unofficial changes made?

A. I'm not saying that there was, I'm just saying if there was something changed at the supplier side, we were not aware of it and we did not approve it, okay?

**(DeGiorgio Deposition, pp. 57-58).**

76. Mr. DeGiorgio's testimony left no doubt that he had spoken with Delphi employees and that they confirmed that there were no changes made to the ignition switch in 2005-2010 Cobalts. This testimony, like the testimony set forth above, was knowingly false and intended to mislead.

77. GM's years-long internal "investigation" into the Subject Vehicles—as well as all of the Old GM documents that were included in the "Purchased Assets" from the bankruptcy sale—provided GM with actual knowledge, long before Dennis Ward's March 2014 injury, of the ignition switch defects in the Subject Vehicles. Notwithstanding these facts, GM continued to fraudulently conceal the nature and extent of the defects from the public, inducing customers, including Dennis Ward, to purchase Subject Vehicles with no knowledge of the existence of these serious and uniform defects, and no provision to avoid the safety risks of operating the Subject Vehicle. Mr. DeGiorgio's deposition testimony in 2013, while appalling, is simply emblematic of the cover-up that was long-running and company-wide.

78. Moreover, throughout the entirety of its corporate existence, GM received numerous and repeated complaints of moving engine stalls and/or power failures in the Subject Vehicles. These complaints are further evidence that GM was fully aware of the ignition switch defect and should have timely announced a recall much sooner than it did.

79. GM was aware of these problems year after year and nationwide, as reflected not only by the internal documents reflecting knowledge and cover-up at high levels, but also in thousands of customer complaints recorded in GM's internal complaint logs and documents. GM received and reviewed complaints of safety issues from customers with Subject Vehicles in nearly every state nationwide. Documents produced by GM pursuant to Order No. 12 in *In re General Motors LLC Ignition Switch Litigation* (14-MC-2543, Dkt. No. 46) show that GM was aware of customer complaints of stalling Subject Vehicles in many of these states and ultimately did nothing about them. These complaints, of course, are in addition to the multiple non-deploy fatalities of which GM became aware and even investigated from July 2009 to the present.

### ***C. GM Issues a Recall—Ten Years Too Late***

80. As pressure from the Melton litigation mounted, GM executives finally felt compelled to act. On January 31, 2014, GM's Field Performance Review Committee and Executive Field Action Decision Committee ("EFADC") finally ordered a recall of some Subject Vehicles.

81. On February 7, 2014, GM, in a letter from Director of Product Investigations and Safety Regulations Carmen Benavides, informed NHTSA that it was conducting a recall of 2005-2007 model year Chevrolet Cobalt and 2007 model year Pontiac G5 vehicles.

82. GM knew that this recall was insufficient in scope. Indeed, GM knew that the same defective ignition switches installed in the Cobalt and G5 vehicles were installed in

Chevrolet HHR, Pontiac Solstice, Saturn Ion, and Saturn Sky vehicles. But GM did not recall these vehicles on February 7.

83. On February 19, 2014, a request for timeliness query of GM's recall was sent to NHTSA by the Center for Auto Safety, a non-profit auto safety group. The timeliness query pointed out that GM had failed to recall all of the vehicles with the defective ignition switches. The February 19, 2014 timeliness query also asked NHTSA to investigate GM's failure to fulfill its legal obligation to report the safety defects in the Subject Vehicles within five days of discovering the defect—a requirement of applicable federal law.

84. On February 24, 2014, GM informed NHTSA it was expanding the recall to include 2006-2007 model year Chevrolet HHR and Pontiac Solstice, 2003-2007 model year Saturn Ion, and 2007 model year Saturn Sky vehicles.

85. GM included an Attachment to the February 24, 2014 letter. In the Attachment, GM, for the first time, admitted that it authorized a change in the ignition switch in 2006.

**Specifically, GM stated:**

On April 26, 2006, the GM design engineer responsible for the Cobalt's ignition switch signed a document approving changes to the ignition switch proposed by the supplier, Delphi Mechatronics. The approved changes included, among other things, the use of a new detent plunger and spring that increased torque force in the ignition switch. This change to the ignition switch was not reflected in a corresponding change in the part number for the ignition switch. GM believes that the supplier began providing the re-designed ignition switch to GM at some point during the 2007 model year.

86. Public criticism in the wake of GM's piecemeal recalls was withering. On March 17, 2014, Mary Barra issued an internal video, which was broadcast to employees. In the video, Ms. Barra acknowledged:

Scrutiny of the recall has expanded beyond the review by the federal regulators at NHTSA, the National Highway Traffic Safety Administration. As of now, two congressional committees have announced that they will examine the issue. And it's been reported that the Department of Justice is looking into this matter. . . . These are serious developments that shouldn't surprise anyone. After all, something went wrong with our process in this instance and terrible things happened.

87. The public backlash continued and intensified. On March 28, 2014, GM again expanded the ignition switch recall to cover all model years of the Chevrolet Cobalt and HHR, the Pontiac G5 and Solstice, and the Saturn Ion and Sky in the United States. This third expansion of the ignition switch recall covered an additional 824,000 vehicles in the United States and raised the number of recalled vehicles to 2,191,146.

88. GM's recalls of the Subject Vehicles were not only untimely; they were completely insufficient to correct the safety-related defects in the Subject Vehicles.

89. To address the safety defect, GM is replacing the defective ignition switches in the Subject Vehicles with a new ignition switch, and providing new keys without slotted key heads. These repairs fail to address the design defect that causes the key fob/chain to hang too low on the steering column, and fail to address the defective airbag system, which disables the airbag immediately when the engine shuts down. Thus, even when the ignition switches and keys are replaced, a defective condition will still exist in the Subject Vehicles and the potential will continue to persist for a driver to contact the key chain and inadvertently turn the key from the "run" to the "accessory/off" position.

90. GM notified owners and lessees of the Subject Vehicles by letter beginning in late February of 2014. GM's recall letter minimizes the risk of the ignition switch defect, indicating that ignition problems would occur only "under certain conditions" and emphasizing that the risk increases if the "key ring is carrying added weight . . . or your vehicle experiences rough road conditions."

91. On May 16, 2014, GM agreed to a civil penalty of \$35 million—the maximum permitted by law—for its failure to timely notify NHTSA of the ignition switch defect. As part of its agreement, GM agreed to implement numerous internal reforms to improve its response to product defect issues in the future.

92. GM later terminated fifteen employees for their participation in the ignition switch cover-up. Two of those employees, Design Release Engineer Ray DeGiorgio and Gary Altman, were intimately involved in the development—and concealment—of the defective ignition switches, and both were longtime employees of Old GM and New GM.

93. In the months that followed the initial ignition switch recalls, GM finally began to acknowledge that it had been ignoring safety concerns in its vehicles for years. To date, GM has announced over 35 recalls since February 2014, and it has recalled over 26.6 million vehicles in the past eight months. This number is staggering; indeed, no car manufacturer has ever recalled as many vehicles in a single year.

#### **D. GM Creates an Inadequate Settlement Fund**

94. GM has acknowledged that the ignition switch defect has caused at least thirteen deaths and over 50 accidents. Independent safety groups put this number far higher: the Center for Auto Safety, for example, estimates that there have been 303 deaths associated with the Saturn Ion and Chevrolet Cobalt vehicles alone. The actual number of deaths and accidents for all Subject Vehicle models is expected to be significantly higher than GM's estimate.

95. In April 2014, under intense scrutiny from Congress and the Department of Justice, Mary Barra announced that GM would retain attorney Kenneth Feinberg to implement a

claims facility to amicably resolve personal injury and wrongful death claims associated with the ignition switch defect. Ms. Barra's announcement was greeted with much fanfare on Capitol Hill and in the press.

96. On June 30, 2014, Mr. Feinberg unveiled the GM Ignition Compensation Claims Resolution Facility (hereinafter the "GM Claims Facility" or "Facility"). The GM Claims Facility offers compensation to three categories of victims:

- Those who were killed in an accident involving certain Subject Vehicles;
- Those who suffered a "Category One" injury in an accident involving certain Subject Vehicles. A Category One injury is defined as a "quadriplegic injury, paraplegic injury, double amputation, permanent brain damage requiring continuous home medical assistance, or pervasive burns encompassing a substantial part of the body"; and
- Those who suffered a "Category Two" injury in an accident involving certain Subject Vehicles. A Category Two injury is generally defined as an injury requiring one or more nights of hospitalization within 48 hours of the accident.

97. In addition to these injury thresholds, the GM Claims Facility does not treat all Subject Vehicles equally. Rather, individual claimants injured or killed in accidents involving any Subject Vehicle of model year 2007 or earlier are eligible for compensation. Claimants in Subject Vehicles whose model year is 2008 or later, however, are eligible only upon proof that (i) the original ignition switch was replaced prior to the accident in question, and (ii) the replacement switch was one bearing Part Number 10392423.

98. According to the GM Claims Facility FAQ, this distinction makes sense because Subject Vehicles of model year 2007 and earlier "had defective ignition switches installed at the time of manufacture." Subject Vehicles whose model year is 2008 or later, however, allegedly "did not have defective ignition switches installed during manufacture." GM has thus taken the position (and excluded from eligibility) those Subject Vehicles that were manufactured with the ignition switches as redesigned by Ray DeGiorgio in 2006. In other words, GM (and the Facility it implemented) denies that the ignition switches were still defective following DeGiorgio's redesign.

99. Thus, GM refuses to acknowledge what GM's engineers have long known— the defect in the ignition switches is not limited to inadequate torque performance, but also includes the low placement of the ignition on the steering cylinder as well as the airbag system that is disabled when the ignition is in the "accessory" or "off" position. GM's FPE team recognized these essential aspects of the safety defect as recently as 2012 when they proposed placing a shroud over the ignition and/or moving the ignition higher on the steering column.

100. Even if the ignition switch defect was purely an issue of inadequate torque



performance, the evidence still shows that the ignition switches were defective even after DeGiorgio's 2006 redesign. In May of 2012, GM's FPE team tested the ignition switches in dozens of Subject Vehicles, many of them model years 2008 and 2009. In these tests, GM engineers found that the ignition switches for these 2008 and 2009 model year Subject Vehicles by and large failed to meet GM's torque specifications for the ignition switch.

101. Further, GM's own investigation into airbag non-deployment events in Chevrolet Cobalt vehicles identified over 250 non-deploy crashes involving 2008-2010 Cobalts. Upon information and belief, GM has knowledge of numerous non-deploy incidents in Subject Vehicles of model year 2008 and later in which the ignition switch was not replaced prior to the relevant incident. Although these vehicles have thus exhibited evidence of the ignition switch defect, they are not eligible for compensation from the Claims Facility.

102. What is more, until GM recalled 2008 and later model year Subject Vehicles, it had never notified the owners of those vehicles that they should remove all items from their key chains and/or avoid jarring road conditions or contacting the ignition key with one's knee. GM knew that any of these scenarios could cause the ignition switches in later model year Subject Vehicles to fail, but it did nothing to notify its customers of these facts.

103. In truth, the problems in earlier model year Subject Vehicles and later model year Subject Vehicles are the same. The ignitions are placed dangerously low on the steering column, and the amount of torque needed to hold the ignition key in place under normal driving conditions is insufficient.

104. The ignition switch in Named Plaintiffs' Subject Vehicles is defective. It is incapable of withstanding ordinary and normal movement and/or pressure. When the ignition switch inadvertently turned to the "accessory" or "off" position, it was because the switch was unable to hold the "run" position, either because the torque performance was inadequate or because the switch inadvertently and unexpectedly moved while the vehicle traveled over rough or uneven roadway. The GM-created Claims Facility is therefore wrong to exclude late model years of Subject Vehicles on the theory that the ignition switches, following DeGiorgio's redesign, are not defective. These ignition switches are demonstrably defective.

105. GM's arbitrary exclusion of these vehicles is simply an attempt to contain its liability—a tactic that contradicts GM CEO Mary Barra's public statements. In her April 1, 2014 testimony before Congress, Ms. Barra assured legislators and the public that:

General Motors want[s] to do the right thing for our customers, and that's why we feel this is an extraordinary situation. . . . [W]e will make the best decisions for our customers, recognizing that we have legal obligations and responsibilities as well as moral obligations. We are committed to our customers, and we are going to work very hard to do the right thing for our customers.



Ten weeks later, Ms. Barra continued with her public assurances, telling Congress that GM “want[s] to capture [in the Facility] every single person who has suffered serious physical injury or lost a loved one” as a result of the defective ignition switches.

106. GM’s assurances are cold comfort for Named Plaintiffs. Instead of fulfilling its assurances, GM waited until June 30, 2014, after congressional and public pressure had significantly subsided, to announce an artificial distinction between vehicles that are recalled for precisely the same defect with precisely the same disastrous safety risks. GM’s exclusion of Named Plaintiffs’ Subject Vehicles in the settlement program, and others like it, is highly suspect, calls into question the commitment of GM to its victims and shows that the Claims Facility is not a viable remedy for many victims of GM’s defective vehicles.

107. Named Plaintiffs should have the option to seek fair and expeditious compensation through the GM-created Claims Facility, but its protocols arbitrarily and unreasonably exclude their Subject Vehicles from eligibility. Once again, GM has offered half-measures where it should fully and completely rectify its past mistakes.

## **VI. TOLLING OF THE STATUTE OF LIMITATION**

108. Old GM sold the Subject Vehicles at issue in this case prior to the filing of this action. Any statutes of repose or limitation are tolled, however, because of New GM’s fraudulent concealment of the ignition switch defect, and conduct equivalent to that required for a finding of willful and wanton conduct against GM.

109. Further, GM was under a continuous duty to disclose to Named Plaintiffs the true character, quality, and nature of the Subject Vehicles. GM actively concealed the true character, quality, and nature of the vehicles and knowingly made misrepresentations about the quality, reliability, characteristics, and performance of the vehicles. Named Plaintiffs reasonably relied upon GM’s knowledge and affirmative representations that its vehicles—including the Subject Vehicles—were safe. Based on the foregoing, GM is estopped from relying on any statutes of limitations in defense of this action.

110. Further, Named Plaintiffs had no realistic ability to discern that the Subject Vehicles were defective until—at the earliest—the ignition switch defect caused a sudden unintended power failure. Even then, Named Plaintiffs had no reason to know the sudden loss of power was caused by a defect in the ignition switch because of GM’s active concealment of the ignition switch defect.

111. The Named Plaintiffs incorporate each and every paragraph above as if fully set forth herein. Each of the Named Plaintiffs listed in Exhibit “A” asserts a loss of vehicular control arising from an ignition switch defect of a GM vehicle resulting in death and/or serious personal injuries.

**VII. CLAIMS FOR RELIEF**

***Claim 1: Negligence, Gross Negligence, Recklessness***

112. The Named Plaintiffs re-allege as if fully set forth, each and every allegation set forth herein.

113. Under the Agreement wherein New GM acquired certain Old GM assets, New GM expressly assumed liability for post-sale accidents involving Old GM vehicles causing personal injury, loss of life or property damage. New GM also acquired knowledge of Old GM's activities and the defective ignition switch via the mind of the employees, officers, managers, books and records obtained and/or acquired as a result of the Agreement and subsequent Sale Order. Thus, the duties of Old GM are part of the foundation for the liability assumed by New GM. Further, as identified therein, the Named Plaintiffs have claims for post-sale accidents involving Old GM vehicles that caused personal injury, loss of life or property damage and New GM is therefore expressly liable to these Plaintiffs.

114. Old GM and New GM owed Named Plaintiffs a duty to design, manufacture, fabricate, assemble, inspect, market, distribute, sell, and/or supply products in such a way as to avoid harm to persons using them such as Named Plaintiffs.

115. Old GM and New GM owed the Named Plaintiffs a duty to detect known safety defects in GM vehicles.

116. Old GM and New GM owed the Named Plaintiffs a duty, once it discovered the ignition switch defect, to provide thorough notice of the defects, including a warning that the defective vehicles should not be driven until an appropriate repair procedure is developed and performed.

117. Old GM and New GM owed the Named Plaintiffs a duty, once it discovered the ignition switch defect, to ensure that an appropriate repair procedure was developed and made available to drivers.

118. Old GM and New GM knew that their customers, such as the Named Plaintiffs, expect that the company will employ all reasonable efforts to detect safety defects, warn drivers of their existence, and develop and make available an appropriate repair procedure.

119. Old GM and New GM's efforts to discover, provide notice of, and provide repair procedures for safety related defects exist for the benefit of the Named Plaintiffs and other drivers of GM vehicles. Old GM and New GM were aware that by providing maintenance and repair information and assistance, including through its authorized dealerships, Old GM and New GM had a responsibility to the Named Plaintiffs and other drivers to take the reasonable measures listed above.

120. By reason of New GM's assumption of liability under the Agreement for post-sale accidents involving Old GM vehicles causing personal injury, loss of life or property damage, the failures of Old GM described above that contributed to or were causally connected to the injuries sustained by Named Plaintiffs were among the liabilities of Old GM assumed by new GM.

121. Independent of any failures by Old GM as described herein, between July 10, 2009 and March 2014, New GM breached its duties to the Named Plaintiffs by failing to provide appropriate notice of and repair procedures for the ignition switch defect in the named Plaintiffs' vehicles. In doing so, new GM departed from the reasonable standard of care required of it.

122. It was foreseeable that if the New GM did not provide appropriate notice and repair procedures for the defect, the Named Plaintiffs and other drivers would be endangered.

123. The Named Plaintiffs' injuries were reasonably foreseeable to Old GM and New GM.

124. The Named Plaintiffs could not through the exercise of reasonable diligence have prevented the injuries caused by Old GM and New GM's negligence and gross negligence.

125. Old GM and New GM's acts and omissions, when viewed objectively from the actor's standpoint, involved an extreme degree of risk, considering the probability and magnitude of the potential harm to others. Old GM and new GM nevertheless proceeded with conscious indifference to the rights, safety and welfare of others.

## **Claim II: Fraud by Non Disclosure**

126. The Named Plaintiffs re-allege as if fully set forth, each and every allegation set forth herein.

127. As early as 2001, during pre-production development of the Saturn Ion, Old GM became aware of issues relating to the ignition switch "passlock" system. The 2001 report states that the problem included a "low detent plunger force" in the ignition switch.

128. In 2003, before the launch of the 2005 Cobalt, Old GM became aware of incidents wherein the vehicle engine would suddenly lose power in the event the key moved out of the "run" position when the driver inadvertently contacted the key or steering column. An investigation was opened and, after consideration of lead-time required and the cost and effectiveness of potential solutions, the investigation was closed with no action taken.

129. As set forth above, from July 2009 to the present, New GM intentionally concealed or failed to disclose material facts from the Named Plaintiffs, the public, and NHTSA.

130. Additionally, from its inception in 2009, New GM possessed independent knowledge of the defects in the Named Plaintiffs' vehicles and the need to undertake multiple design steps to resolve those defects to prevent injury and economic harm to vehicle owners such as Named Plaintiffs. This knowledge was based, in part, on the information from records, files, reports and other documents and materials regarding the defective ignition switch maintained by Old GM, all of which were included in the assets purchased by New GM during the bankruptcy sale.

131. Old GM had a duty to disclose facts to the Named Plaintiffs and Old GM knew: (1) that the Named Plaintiffs were ignorant of the material facts that New GM did not disclose and/or intentionally concealed; and (2) the Named Plaintiffs did not have an equal opportunity to discover the material facts that New GM did not disclose and/or intentionally concealed. Old GM's fraud, fraudulent concealment and fraudulent non-disclosure were all components of the subject incidents of the Named Plaintiffs. Because New GM expressly assumed liability for post-sale accidents causing personal injury, loss of life or property damage, New GM is liable to the Named Plaintiffs.

132. Specifically, under the Agreement wherein New GM acquired certain Old GM assets, New GM expressly assumed liability for post-sale accidents involving Old GM vehicles causing personal injury, loss of life or property damage. New GM also acquired knowledge of Old GM's activities and the defective ignition switch via the mind of the employees, officers, managers, books and records obtained and/or acquired as a result of the Agreement and subsequent Sale Order. Thus, the duties of Old GM are part of the foundation for the liability assumed by New GM. Further, as identified therein, the Named Plaintiffs have claims for post-sale accidents involving Old GM vehicles that caused personal injury, loss of life or property damage, and New GM is therefore expressly liable to these Plaintiffs.

133. By reason of New GM's assumption of liability under the Agreement for post-sale accidents involving Old GM vehicles causing personal injury, loss of life or property damage, the failures of Old GM described above that contributed to or were causally connected to the injuries sustained by Named Plaintiffs were among the liabilities of Old GM assumed by New GM. Independent of any failures by Old GM as described herein, between July 10, 2009 and March 2014, New GM breached its duties to the Named Plaintiffs by failing to disclose knowledge of the defective ignition switch to Named Plaintiffs.

134. New GM had a duty to disclose the facts to the Named Plaintiffs and New GM knew: (1) that the Named Plaintiffs were ignorant of the material facts that New GM did not disclose and/or intentionally concealed; and (2) the Named Plaintiffs did not have an equal opportunity to discover the material facts that New GM did not disclose and/or intentionally concealed.

135. By failing to disclose these material facts, new GM intended to induce the Named Plaintiffs to take some action or refrain from acting.

136. The Named Plaintiffs relied on New GM's non-disclosure and they were injured as a result of acting without knowledge of the undisclosed facts.

### **Claim III: Strict Liability**

137. The Named Plaintiffs re-allege as if fully set forth, each and every allegation set forth herein.

138. Old GM and New GM, at all times relevant to this action, were engaged in the design, testing, manufacture, distribution, and sale of automobiles, including the Subject Vehicles. The Subject Vehicles were expected to and did reach users and consumers without substantial change in the condition in which it was sold.

139. The Subject Vehicles were in a defective condition creating risk of harm to a user or a consumer, including Named Plaintiffs.

140. The defects set forth herein caused the Named Plaintiffs' injuries.

141. Under the Agreement wherein New GM acquired certain Old GM assets, New GM expressly assumed liability for post-sale accidents involving Old GM assets, New GM expressly assumed liability for post-sale accidents involving Old GM vehicles causing personal injury, loss of life or property damage. As identified therein, the Named Plaintiffs have claims for post-sale accidents involving Old GM vehicles that caused personal injury, loss of life or property damage and New GM is therefore expressly liable to these Plaintiffs.

142. These injuries and losses were caused by New GM's designing, manufacturing, fabricating, assembling, inspecting, marketing, distributing, selling and/or supplying the subject automobile in a defective condition for which it is strictly liable to the Named Plaintiffs pursuant to Restatement (Second) of Torts § 402A. Alternatively, the injuries and losses were caused by Old GM's designing, manufacturing, fabricating, assembling, inspecting, marketing, distributing, selling and/or supplying the subject automobile in a defective condition for which New GM is strictly liable to the Named Plaintiffs pursuant to Restatement (Second) of Torts § 402A because these liabilities were expressly assumed by New GM.

143. By reason of New GM's assumption of liability under the Agreement for post-sale accidents involving Old GM vehicles causing personal injury, loss of life or property damage, the failures of Old GM described above that contributed or were causally connected to the injuries sustained by Named Plaintiffs were among the liabilities of Old GM assumed by New GM. Independent of any failures by Old GM as described herein, between July 10, 2009 and March 2014, New GM breached its duties owed to the Named Plaintiffs as described herein.

### **Claim IV: Breach of Implied Warranty of Merchantability**

144. Named Plaintiffs re-allege as if fully set forth, each and every allegation set forth herein.

145. Named Plaintiffs claim that they were harmed by the Subject Vehicles sold by GM because the Subject Vehicles and their ignition switch, power and airbag systems did not have the quality that a buyer would expect.

146. At the time of purchase, GM was in the business of selling cars and held itself out as having special knowledge or skill regarding such products.

147. The Subject Vehicles were not fit for the ordinary purpose for which such products are used.

148. Named Plaintiffs were harmed. The failure of the Subject Vehicles and their ignition switch, power and airbag systems to have the expected quality and be fit for its ordinary purpose was a substantial factor in causing Named Plaintiffs' harm and the damages that Plaintiffs have suffered and seek recovery for in this action.

#### **VIII. DAMAGES**

149. The Named Plaintiffs pray for damages against the Defendant in a sum of money in excess of the jurisdictional amount of Seventy-Five Thousand Dollars (\$75,000.00) plus costs and any other relief to be deemed just and equitable to which they are entitled.

#### **IX. PUNITIVE DAMAGES**

150. The Named Plaintiffs re-allege as if fully set forth, each and every allegation set forth herein.

151. The Named Plaintiffs would further show that the clear and convincing evidence in this case, as alleged herein, will show that GM consciously or deliberately engaged in oppression, fraud, wantonness, and/or malice in concealing the defect in the Subject Vehicles and by failing to recall the vehicles in a timely manner. GM had actual, subjective awareness of the risk involved but nevertheless proceeded with indifference to the rights, safety, or welfare of others, including Plaintiff. Therefore, punitive damages are sought and should be assessed against the Defendant.

#### **X. PRAYER**

For the foregoing reasons, Named Plaintiffs pray that the Defendant be cited to appear and answer herein, and that upon a final hearing of the cause, judgment be entered for each of the Named Plaintiffs against Defendant for actual damages, as alleged, and exemplary damages; together with pre-judgment interest (from the date of injury through



the date of judgment) at the maximum rate allowed by law; post-judgment interest at the legal rate, costs of court; and such other and further relief to which Named Plaintiffs may be entitled at law or in equity.

Dated: September 21, 2015

Respectfully submitted,



Justin T. Bailey Esq., NY Bar No. 5034269  
David W. Hannum Esq., NJ Bar No. 036962006  
Perry R. Sanders Jr. Esq., LA Bar No. 01577  
Sanders Law Firm, LLC  
31 N Tejon Street, Suite 400  
Colorado Springs, CO 80903  
T: (719) 630-1556  
F: (719) 630-700

**JURY DEMAND**

Pursuant to Federal Rule of Civil Procedure 38(b), Plaintiffs demand a trial by jury of any and all issues in this action so triable of right.

Dated: September 21, 2015

Respectfully submitted,



Justin T. Bailey Esq., NY Bar No. 5034269  
David W. Hannum Esq., NJ Bar No. 036962006  
Perry R. Sanders Jr. Esq., LA Bar No. 01577  
Sanders Law Firm, LLC  
31 N Tejon Street, Suite 400  
Colorado Springs, CO 80903  
T: (719) 630-1556  
F: (719) 630-7004

# EXHIBIT "A"

Name of Plaintiff	Residency	Car Type	VIN #	Accident Date	Accident City/ State
Haley Campbell	Georgia	Chevy Cobalt	1G1AM15B667826305	11/11/12	Monroe, GA
Thomas Hayes	Georgia	Chevy HHR	NO Vin #- Rental Car	12/01/06	Minnesota
William Tenley	Pennsylvania	Chevy Cobalt	1G1AK15F267717476	07/24/08	Clear Springs, MD
Pamela Cannon	Oklahoma	Chevy HHR	3GNDA23P765589544	02/12/14	Chandler, Oklahoma
Jeffrey Noice	Florida	Saturn Ion	1G8AJ55F06Z124828	05/11/10	Jacksonville, FL
Michael Lewis	Florida	Chevy HHR	3GNDA23D96S657638	04/16/13	Newport Ritchey, FL
Alfred Schmitt	N Carolina	Chevy Cobalt	1G1AK52F157670161	10/04/10	Tabor City, NC
Kevin Moore	Ohio	Chevy Cobalt	1G1AK15F867796457	08/13/14	Norwalk, OH
Alysha Nedd	Wisconsin	Chevy Cobalt	1G1AK55F667682948	01/15/14	Madison, WI
Sharon Reid	Ohio	Chevy Cobalt	1G1AT58H897154598	04/25/13	Mifflin, OH
David Turner	Kentucky	Saturn Ion	1G8AJ52F73Z129461999	03/25/13	Robards, KY
Ann Clark	Tennessee	Chevy Cobalt	1G1AL15177175141	05/29/14	Summerville, TN
Yolanda Forrester	Georgia	Chevy Cobalt	1G1AX55F58773323	05/23/11	Cuthbert, GA
Towana Thomas	California	Saturn Ion	1G8AJ52F13Z108377	03/04/14	Antioch, CA
Erick Hilton	N. Carolina	Chevy Cobalt	1G1AL52F757604663	06/20/14	Roanoke Rapids, NC
Marshall Hackett	California	Saturn Ion	1G8AJ52F13Z108377	03/04/14	Antioch, CA
Emily Debusk	Virginia	Chevy Cobalt	1G1AL15F377228647	05/22/13	Hampton, VA
Velma Alvarado	Texas	Chevy Cobalt	1G1AT58H997272966	02/12/14	Selma, TX
Donna Buford-Russell	Michigan	Chevy Impala	2GIWTS8K479147693	6/25/11	Dearborn, MI
Johnnie Topping	Michigan	Chevy Impala	2GIWTS8K479147693	6/25/11	Dearborn, MI
Virginia Schmid	Pennsylvania	Chevy Cobalt	1G1AK58F5872322478	9/20/13	Nockamixon Twn. PA
Mary Chester	Pennsylvania	Chevy Cobalt	1G1AK58F5872322478	9/20/13	Nockamixon Twn. PA
Mocha Myers	Mississippi	Pontiac grand Prix	2G2WPS22051288250	5/13/11	Gulfport, MS

Jennifer Dahlk	Wisconsin	Oldsmobile Alero	Ig3NL52EO21C102466	10/24/12	Madison WI
Betty Gist	S. Carolina	Chevy HHR	3GNBAADLXAS504046	3/18/11	Greenville, SC
Bobby Myers	Louisiana	Pontiac Grand Prix	2G2WPP552461123654	5/6/13	Opelousas, LA
Nora Skaggs	Ohio	Chevy Equinox	2GNALBEK5D6211460	7/17/14	New Boston, OH